



电子元器件系列 (中国.厦门)

www.rf-china.com RF-Micom co.,Ltd

EMail:sales@rf-china.com

Telephone:0086-592-5713956 Fax:5201617



Products Affected / Intel Ordering Codes:

Current Part Number Marking	Affected Product Code	Pre-conversion MM#	Post-conversion MM#
CL-PD6710-VC-B	DZPD6710VCB	832520	No Change
CL-PD6720-QC-B	SPD6720QCB	832521	No Change
CL-PD6722-QC-CE	SPD6722QCCE	832530	No Change
CL-PD6722-VC-CE	DZPD6722VCCE	832532	No Change
CL-PD6729-QC-C	SPD6729QCC	832533	No Change
CL-PD6729-QC-E	SPD6729QCE	832534	No Change
CL-PD6729-VC-E	DZPD6729VCE	832535	No Change
CL-CD1283-10QC-E	SCD128310QCE	832512	No Change
CL-CD1284-10QC-E	SCD128410QC-E	832513	No Change
CL-CD1400-10QC-J	SCD140010QCJ	832514	No Change
CL-CD1865-10QC-B	SCD186510QCB	832515	No Change
CL-CD2231-10QC-D	SCD223110QCD	832550	No Change
CL-CD2401-10QC-M	SCD240110QCM	832516	No Change
CL-CD2402-10QC-M	SCD240210QCM	832517	No Change
CL-CD2431-10QC-D	SCD243110QCD	832518	No Change
CL-CD2481-10QC-D	SCD248110QCD	832519	No Change

Reference Documents / Attachments:

Typical current mark:



Additional new mark:



- **Additional current country codes include Singapore-V and Singapore-S**
(Last line on the Marking)